

1. Initiator		2. Type of Review		3. RID Number
Name	Feodoroff, Barry	<input type="checkbox"/>	General Document Review	00200-110
Organization	LMSMSS	<input checked="" type="checkbox"/>	PDR, CDR, ABR , PPR (circle)	
Phone	861-2233	<input type="checkbox"/>	Other _____	
Fax				
5a. Doc. Number	84K00200	6. Doc. Name	System Level Specification (SLS)	
5a. Doc. Revision	Pre-Release 1			
6. Name of RID Team		SLS RID Review Team		
7. Problem				
<p>Paragraphs 2.2.4.3 System Viewers: 1.) While this paragraph does not list the system viewers (rather it refers to the display viewer application software), the subparagraph begin to list the some, <u>but not all</u>, the detail software requirements for system viewers.</p> <p>2.) Identifying system viewer requirements implies a software architecture that is not specified in the SLS.</p>				
8. Recommendation				
<p>1.) Since the subparagraphs do not collect all the requirements for the system viewer software (it has yet to be developed), reference a System Viewers CSCI, and move the subparagraphs to the CSCI.</p> <p>2.) Include a section in the SLS that covers the CLCS Software Architecture requirements.</p>				
9. Impact if recommendation not implemented				
<p>1) There will be less need to update the SLS to reflect changes as the system messages software is developed.</p> <p>2) Acknowledge the CLCS proposed software architecture.</p>				
			Initiator - Signature _____	Submission Date _____
10. Team Recommendation		11. Action Required		
<input type="checkbox"/> Accepted <input checked="" type="checkbox"/> Rejected <input type="checkbox"/> Study <input type="checkbox"/> Withdrawn <input type="checkbox"/> Deferred to CLCS CCB Screening Panel Comments See Attached. RID Team Manager - Signature _____		<input type="checkbox"/> Update Document <input type="checkbox"/> Study <input type="checkbox"/> Other (specify) _____ Comments		
12. Final RID Closure Action		13. Additional Comments/Notes		
<input type="checkbox"/> RID to be incorporated in next revision <input type="checkbox"/> RID to be incorporated in other (specify) RID Team Manager - Signature _____				

Due NO LATER THAN April 30, 1997

Response Attachment 200-110

- 1) The RID Management Team (RMT) acknowledges the fact that the top level requirements for System Viewers are not developed at this time. However, Appendix C provides a list of CCMS Command Processor applications (essentially the System Viewers of the era), and the requirement to port, or provide equivalent function in CLCS. It is the position of the RMT that the addition of the requirements to the SLS doesn't add sufficient value to warrant expending the labor and time that inclusion of such requirements would entail.
- 2) RID 109 — written by the same author requested that a section of CLCS Architecture Requirements be developed and placed into the SLS. That RID was rejected. Refer to the attachment for RID 109 for the rationale for rejection.